ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0282	3rd A Crs Maheshwari Nagar	Selection Corner
Segment No.	**Total Length (m)**	
13/S-W0282/S015957	260.33	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	260.33	77.516192	13.049753	77.518114	13.048344	Prashanthnagara main road	S Ramesh road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of RCC drain in 1st cross road at Prashantha nagara in Ward No.13, Shetty halli Sub Division	2500000	2016
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender		013-16-000003
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/77/15-16	24/03/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B Muniraju		0.00
Phone No.	**E-Mail ID**	
9448512985		

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike
Dasarahalli Division, Bangalore-560057

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Nagabhushan
Date of Inspection	**Remarks**	
05/11/2016		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

EXECUTIVE ENGINEER
Dasarahalli Division, Bangalore-560057

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0282

Date: 05/11/2016 Time: 14:02:21 RH 20161105140221